

DAFTAR GAMBAR

Gambar 2.1 Arsitektur 4G	5
Gambar 2.2 Perhitungan Jarak dan Sudut Mechanical Tilting	11
Gambar 3.1 Flowchart pegerjaan Proyek Akhir	13
Gambar 3.2 Data Komplain dari website M5	14
Gambar 3.3 Survey Lokasi Komplek Nata Endah Cihanjuang Cimahi	16
Gambar 3.4 Flowchart drivetest	17
Gambar 3.5 Rute drivetest	18
Gambar 3.6 Serving PCI	18
Gambar 3.7 Site <i>overshoot</i>	19
Gambar 3.8 Nilai RSRP before	20
Gambar 3.9 Bad SINR	21
Gambar 4.1 flowchart Optimasi	23
Gambar 4.2 <i>Serving</i> PCI	24
Gambar 4.3 Jarak Site ke lokasi	25
Gambar 4.4 <i>Serving</i> PCI Dominan	26
Gambar 4.5 Azimuth Lokasi pada Software Google Earth	27
Gambar 4.6 Sektor 2 Before Bearing Antenna	28
Gambar 4.7 kontur bumi sektor 2 ke lokasi	28
Gambar 4.8 Azimuth Sektor 3	29
Gambar 4.9 sektor 3 Before Bearing Antenna	29
Gambar 4.10 Kontur bumi Sektor 3 Ke lokasi komplain	30
Gambar 4.11 Jarak Site <i>overshoot</i> ke lokasi	30
Gambar 4.12 Kontur bumi site alun-alun cimahi	31
Gambar 4.13 Kontur bumi site setelah dikurangi jarak jangkauannya	32
Gambar 4.14 Azimuth site after tilting	33
Gambar 4.15 Database Sektor 2 After Bearing	35
Gambar 4.16 Database Sektor 3 After Bearing	35
Gambar 4.17 <i>Serving</i> PCI After	36
Gambar 4.18 RSRP After	36

Gambar 4.19 SINR After.....	37
Gambar 4.20 Serving PCI after dtowntil.....	38
Gambar 4.21 Nilai RSRP After	38
Gambar 4.22 SINR After.....	39
Gambar 4.23 Serving PCI Before.....	39
Gambar 4.24 Serving PCI After Bearing.....	40
Gambar 4.25 Serving PCI After downtilt.....	41
Gambar 4.26 Perbandingan serving PCI	41
Gambar 4.27 Nilai RSRP before	42
Gambar 4.28 Nilai RSRP after bearing	42
Gambar 4.29 Nilai RSRP after downtilt.....	43
Gambar 4.30 Perbandingan nilai RSRP	43
Gambar 4.31 Nilai SINR before	44
Gambar 4.32 Nilai SINR after bearing.....	44
Gambar 4.33 Nilai SINR <i>after downtilt</i>	45
Gambar 4.34 Perbandingan Nilai SINR	46