

DAFTAR GAMBAR

Gambar I.1 Persentase Kemunculan <i>Defect</i>	13
Gambar I.2 Frekuensi Kemunculan Jenis <i>Defect</i>	16
Gambar I.3 Alur Produksi.....	17
Gambar I.4 Fishbone diagram penentuan tekanan mesin tidak sesuai dengan bahan	19
Gambar II.1. CTQ <i>Tree</i>	31
Gambar II.2 Fase Pengembangan Produk.....	32
Gambar II.3 Proses QFD.....	34
Gambar II.4 <i>Interrelated Matrices</i>	34
Gambar III.1 Sistemasi perancangan.....	38
Gambar IV.1 <i>T-shirt</i>	44
<i>Gambar IV.2 House Of Quality</i>	47
Gambar IV.3 Sensor PCB Servo GC6-28D.....	56
Gambar IV.4 <i>Controller</i> Arduino R3 Atmega 328P.....	56
Gambar IV.5 Sensor Dimer Dimmer 2000W.....	57
Gambar IV.6 Alat bantu usulan alarm mesin jahit.....	59
Gambar IV.7 <i>flowchart</i> Penggunaan alat bantu usulan alarm mesin jahit.....	60