

DAFTAR ISI

LEMBAR PENGESAHAN	Error! Bookmark not defined.
LEMBAR PERNYATAAN ORISINALITAS	Error! Bookmark not defined.
ABSTRAK	Error! Bookmark not defined.
ABSTRACT	Error! Bookmark not defined.
KATA PENGANTAR	Error! Bookmark not defined.
UCAPAN TERIMA KASIH	Error! Bookmark not defined.
DAFTAR ISI	1
DAFTAR GAMBAR.....	Error! Bookmark not defined.
DAFTAR TABEL	Error! Bookmark not defined.
DAFTAR ISTILAH.....	Error! Bookmark not defined.
BAB I	Error! Bookmark not defined.
PENDAHULUAN.....	Error! Bookmark not defined.
1.1 Latar Belakang	Error! Bookmark not defined.
1.2 Rumusan Masalah	Error! Bookmark not defined.
1.3 Tujuan & Manfaat	Error! Bookmark not defined.
1.4 Batasan Masalah.....	Error! Bookmark not defined.
1.5 Metode Penelitian.....	Error! Bookmark not defined.
BAB II	Error! Bookmark not defined.
HSPA+ (EVOLVED HSPA).....	Error! Bookmark not defined.
2.1 KONSEP JARINGAN HSPA+	Error! Bookmark not defined.
2.2 MIMO.....	Error! Bookmark not defined.
2.2.1 Transmisi data HSDPA-MIMO	Error! Bookmark not defined.
2.2.2 Rate control untuk HSDPA-MIMO	Error! Bookmark not defined.
2.2.3 Hybrid ARQ dengan soft combining untuk HSDPA-MIMO.....	Error! Bookmark not defined.
2.2.4 Modulasi tingkat tinggi	Error! Bookmark not defined.
2.2.5 Continuous packet connectivity.....	Error! Bookmark not defined.
2.3 Peningkatan protocol layer 2.....	Error! Bookmark not defined.
2.4 Advanced receivers	Error! Bookmark not defined.
2.5 ARSITEKTUR JARINGAN HSPA+	Error! Bookmark not defined.
2.5.1 UE (User Equipment)	Error! Bookmark not defined.
2.5.2 UTRAN (UMTS Terrestrial Radio Acces Network).....	Error! Bookmark not defined.
2.5.3 CN (Core Network)	Error! Bookmark not defined.
2.6 Alokasi Frekuensi HSPA	Error! Bookmark not defined.
2.7 Parameter Penanganan Interferensi	Error! Bookmark not defined.
2.7.1 RTWP	Error! Bookmark not defined.
2.8 Interferensi	Error! Bookmark not defined.
2.8.1 Sumber Interferensi.....	Error! Bookmark not defined.

2.9	Spektrum Analyzer	Error! Bookmark not defined.
2.10	Pengertian Dan Fungsi Dasar Antena	Error! Bookmark not defined.
2.11	Repeater.....	Error! Bookmark not defined.
2.12	Aplikasi U2000	Error! Bookmark not defined.
2.13	Uplink Interference Dan Downlink Interference ..	Error! Bookmark not defined.
BAB III.....		Error! Bookmark not defined.
PENANGANAN INTERFERENSI.....		Error! Bookmark not defined.
3.1	Diagram Alir Penanganan Interferensi.....	Error! Bookmark not defined.
3.1.1	Alarm RTWP.....	Error! Bookmark not defined.
3.1.2	Trafik Data.....	Error! Bookmark not defined.
3.2	Pengaruh RTWP terhadap trafik	Error! Bookmark not defined.
3.3	Penanganan Interferensi Eksternal	Error! Bookmark not defined.
3.3.1	Pemindaian Frekuensi.....	Error! Bookmark not defined.
3.2.2	Laporan dan Solusi Interferensi	Error! Bookmark not defined.
3.2.2	Aksi Persuasif Kepada Pemilik Repeater.....	Error! Bookmark not defined.
3.2.3	Penertiban Repeater	Error! Bookmark not defined.
3.2.4	Cek Alarm RTWP.....	Error! Bookmark not defined.
BAB IV		Error! Bookmark not defined.
ANALISA DAN PEMAHASAN		Error! Bookmark not defined.
4.1	Analisa Lokasi suspect repeater	Error! Bookmark not defined.
4.2	Analisa Hasil Pemindaian Spectrum Analyzer	Error! Bookmark not defined.
4.3	Analisa RTWP.....	Error! Bookmark not defined.
4.3	Analisa trafik data HSPA+.....	Error! Bookmark not defined.
BAB V		Error! Bookmark not defined.
KESIMPULAN DAN SARAN		Error! Bookmark not defined.
5.1	Kesimpulan.....	Error! Bookmark not defined.
5.2	Saran.....	Error! Bookmark not defined.
REFERENSI.....		Error! Bookmark not defined.
LAMPIRAN A		Error! Bookmark not defined.