

DAFTAR GAMBAR

Gambar 1.1 Kerusakan Mesin CNC 2017-2019	2
Gambar 1.2 Mesin Toshiba MPE-2160	3
Gambar 2.1 Konsep Maitenance.....	8
Gambar 2.2 Keterangan Laju Kerusakan.....	12
Gambar 2.3 Cost Of Unreliability.....	16
Gambar 3.1 Model Konseptual	23
Gambar 3.2 Sistematika Penyelesaian Masalah.....	25
Gambar 3.3 Sistematika Penyelesaian Masalah (Lanjutan 1)	26
Gambar 5.1 Cost Of Conformance Bahan lain untuk pemeliharaan.....	60
Gambar 5.2 Cost Of Conformance Lubricant	61
Gambar 5.3 Cost Of Noncofromance Exchange Part	62
Gambar 5.4 Cost Of Noncofromance Lost Production Time	64
Gambar 5.5 Cost Of Noncofromance Logistic	65
Gambar 5.6 Cost Of Noncofromance Jam Kerja Untuk Pemeliharaan.....	66